

Results of Water Quality Testing
for
Fairmount Park Elementary

Updated October 31, 2017

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria:

All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			CURRENT STATUS								OK?
			LEAD		CADMIUM		COPPER		IRON		
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	Entry hallway, left 01	P	None	P	None	P	None	P	None	Yes
02	B	Entry hallway, right 01	P	None	P	None	P	None	P	None	Yes
03	B	cafeteria, left 02	P	None	P	None	P	None			Yes
04	B	cafeteria, right 02	P	None	P	None	P	None			Yes
05	B	cafeteria, bottled filler 02	P	None	P	None	P	None			Yes
06	S	kitchen, left 12	P	None	P	None	P	None			Yes
07	S	kitchen, right 12	P	None	P	None	P	None			Yes
08	S	kitchen 12	P	None	P	None	P	None			Yes
09	S	art room 04	P	None	P	None	P	None			Yes
10	S	art room 04	P	None	P	None	P	None			Yes
11	B	gym, left 05	P	None	P	None	P	None			Yes
12	B	gym, right 05	P	None	P	None	P	None			Yes
13	B	gym, bottle filler 05	P	None	P	None	P	None	P	None	Yes
14	S	nurse office 111	P	None	P	None	P	None	P	None	Yes
15	S	work room 113	P	None	P	None	P	None	P	None	Yes
16	S	family room 125	P	None	P	None	P	None	P	None	Yes
17	B	hallway outside custodial 127, left	P	None	P	None	P	None			Yes
18	B	hallway outside custodial 127, right	P	None	P	None	P	None			Yes
19	S/B	classroom 129	P	None	P	None	P	None	P	None	Yes
20	S/B	classroom 201	P	None	P	None	P	None	P	None	Yes
21	S/B	classroom 203	P	None	P	None	P	None	P	None	Yes
22	S/B	work room 204C	P	None	P	None	P	None	P	None	Yes
23	S/B	library 205	P	None	P	None	P	None			Yes
24	S/B	classroom 206	P	None	P	None	P	None			Yes
25	S/B	classroom 208	P	None	P	None	P	None			Yes
26	S/B	classroom 210	P	None	P	None	P	None			Yes
27	B	hallway, outside 210, left	P	None	P	None	P	None			Yes
28	B	hallway, outside 210, right	P	None	P	None	P	None			Yes
29	S/B	classroom 216	P	None	P	None	P	None			Yes
30	S/B	classroom 217	P	None	P	None	P	None			Yes
31	S/B	classroom 218	P	None	P	None	P	None			Yes
32	S/B	classroom 219	P	None	P	None	P	None	P	None	Yes
33	S/B	kindergarten, 220	P	None	P	None	P	None	P	None	Yes
34	B	hallway, outside kindergarten, left	P	None	P	None	P	None	P	None	Yes
35	B	hallway, outside kindergarten, right	P	None	P	None	P	None	P	None	Yes
36	S/B	kindergarten, 221	P	None	P	None	P	None			Yes
37	B	kindergarten, 222	P	None	P	None	P	None			Yes
38	S/B	OT/PT 224	P	None	P	None	P	None			Yes
39	S/B	Special Ed. 226	P	None	P	None	P	None			Yes
40	S/B	special Ed. 227	P	None	P	None	P	None			Yes
41	B	hallway, outside 227, left	P	None	P	None	P	None			Yes
42	B	hallway, outside 227, right	P	None	P	None	P	None			Yes
43	S/B	classroom 300	P	None	P	None	P	None	P	None	Yes
44	B	hallway, outside 301, left	P	None	P	None	P	None	P	None	Yes
45	B	hallway, outside 301, right	P	None	P	None	P	None			Yes

46	S/B	classroom 301	P	None	P	None	P	None			Yes
47	S/B	classroom 302	P	None	P	None	P	None			Yes
48	S/B	classroom 303	P	None	P	None	P	None			Yes
49	S/B	classroom 304	P	None	P	None	P	None			Yes
50	S	classroom 305	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling						Follow-up Sampling 1						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	B	Entry hallway, left 01	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
02	B	Entry hallway, right 01	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
03	B	cafeteria, left 02	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
04	B	cafeteria, right 02	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
05	B	cafeteria, bottled filler 02	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
06	S	kitchen, left 12	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
07	S	kitchen, right 12	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
08	S	kitchen 12	8/13/2014	2	<1		P		8/22/2017	<1	<1		P		P	None
09	S	art room 04	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
10	S	art room 04	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
11	B	gym, left 05	8/13/2014	3	<1		P		8/22/2017	<1	<1		P		P	None
12	B	gym, right 05	8/13/2014	3	1		P		8/22/2017	<1	<1		P		P	None
13	B	gym, bottle filler 05	8/13/2014	3	1		P								P	None
14	S	nurse office 111	8/13/2014	2	<1		P		8/22/2017	1	<1		P		P	None
15	S	work room 113	8/13/2014	3	<1		P		8/22/2017	2	<1		P		P	None
16	S	family room 125	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
17	B	hallway outside custodial 127, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
18	B	hallway outside custodial 127, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
19	S/B	classroom 129	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
20	S/B	classroom 201	8/13/2014	2	<1		P		8/22/2017	<1	<1		P		P	None
21	S/B	classroom 203	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
22	S/B	work room 204C	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
23	S/B	library 205	8/13/2014	<1	<1		P		8/22/2017	1	<1		P		P	None
24	S/B	classroom 206	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
25	S/B	classroom 208	8/13/2014	2	<1		P		8/22/2017	<1	<1		P		P	None
26	S/B	classroom 210	8/13/2014	2	<1		P		8/22/2017	<1	<1		P		P	None
27	B	hallway, outside 210, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
28	B	hallway, outside 210, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
29	S/B	classroom 216	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
30	S/B	classroom 217	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
31	S/B	classroom 218	8/13/2014	3	<1		P		8/22/2017	<1	<1		P		P	None
32	S/B	classroom 219	8/13/2014	1	3		P		8/22/2017	<1	<1		P		P	None
33	S/B	kindergarten, 220	8/13/2014	2	<1		P		8/22/2017	1	1		P		P	None
34	B	hallway, outside kindergarten, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
35	B	hallway, outside kindergarten, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
36	S/B	kindergarten, 221	8/13/2014	<1	<1		P		8/22/2017	1	<1		P		P	None
37	B	kindergarten, 222	8/13/2014	<1	<1		P		8/22/2017	1	<1		P		P	None
38	S/B	OT/PT 224	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
39	S/B	Special Ed. 226	8/13/2014	1	<1		P		8/22/2017	<1	<1		P		P	None
40	S/B	special Ed. 227	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
41	B	hallway, outside 227, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
42	B	hallway, outside 227, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
43	S/B	classroom 300	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
44	B	hallway, outside 301, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
45	B	hallway, outside 301, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
46	S/B	classroom 301	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
47	S/B	classroom 302	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
48	S/B	classroom 303	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
49	S/B	classroom 304	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
50	S	classroom 305	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling						Follow-up Sampling 1						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	B	Entry hallway, left 01	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
02	B	Entry hallway, right 01	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
03	B	cafeteria, left 02	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
04	B	cafeteria, right 02	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
05	B	cafeteria, bottled filler 02	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
06	S	kitchen, left 12	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
07	S	kitchen, right 12	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
08	S	kitchen 12	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
09	S	art room 04	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
10	S	art room 04	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
11	B	gym, left 05	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
12	B	gym, right 05	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
13	B	gym, bottle filler 05	8/13/2014	<1	<1		P								P	None
14	S	nurse office 111	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
15	S	work room 113	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
16	S	family room 125	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
17	B	hallway outside custodial 127, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
18	B	hallway outside custodial 127, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
19	S/B	classroom 129	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
20	S/B	classroom 201	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
21	S/B	classroom 203	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
22	S/B	work room 204C	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
23	S/B	library 205	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
24	S/B	classroom 206	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
25	S/B	classroom 208	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
26	S/B	classroom 210	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
27	B	hallway, outside 210, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
28	B	hallway, outside 210, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
29	S/B	classroom 216	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
30	S/B	classroom 217	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
31	S/B	classroom 218	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
32	S/B	classroom 219	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
33	S/B	kindergarten, 220	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
34	B	hallway, outside kindergarten, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
35	B	hallway, outside kindergarten, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
36	S/B	kindergarten, 221	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
37	B	kindergarten, 222	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
38	S/B	OT/PT 224	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
39	S/B	Special Ed. 226	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
40	S/B	special Ed. 227	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
41	B	hallway, outside 227, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
42	B	hallway, outside 227, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
43	S/B	classroom 300	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
44	B	hallway, outside 301, left	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
45	B	hallway, outside 301, right	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
46	S/B	classroom 301	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
47	S/B	classroom 302	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
48	S/B	classroom 303	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
49	S/B	classroom 304	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None
50	S	classroom 305	8/13/2014	<1	<1		P		8/22/2017	<1	<1		P		P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling						Follow-up Sampling 1						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	B	Entry hallway, left 01	8/13/2014	0.17	0.098		P		8/22/2017	0.134	0.049		P		P	None
02	B	Entry hallway, right 01	8/13/2014	0.185	0.093		P		8/22/2017	0.053	0.025		P		P	None
03	B	cafeteria, left 02	8/13/2014	0.199	0.199		P		8/22/2017	0.123	0.123		P		P	None
04	B	cafeteria, right 02	8/13/2014	0.251	0.189		P		8/22/2017	0.114	0.115		P		P	None
05	B	cafeteria, bottled filler 02	8/13/2014	0.19	0.185		P		8/22/2017	0.126	0.116		P		P	None
06	S	kitchen, left 12	8/13/2014	0.188	0.099		P		8/22/2017	0.16	0.027		P		P	None
07	S	kitchen, right 12	8/13/2014	0.172	0.106		P		8/22/2017	0.126	0.021		P		P	None
08	S	kitchen 12	8/13/2014	0.212	0.238		P		8/22/2017	0.169	0.023		P		P	None
09	S	art room 04	8/13/2014	0.187	0.023		P		8/22/2017	0.134	0.032		P		P	None
10	S	art room 04	8/13/2014	0.25	0.037		P		8/22/2017	0.231	0.034		P		P	None
11	B	gym, left 05	8/13/2014	0.198	0.197		P		8/22/2017	0.199	0.178		P		P	None
12	B	gym, right 05	8/13/2014	0.215	0.216		P		8/22/2017	0.157	0.164		P		P	None
13	B	gym, bottle filler 05	8/13/2014	0.491	0.381		P								P	None
14	S	nurse office 111	8/13/2014	0.248	0.202		P		8/22/2017	0.149	0.132		P		P	None
15	S	work room 113	8/13/2014	0.544	0.242		P		8/22/2017	0.434	0.075		P		P	None
16	S	family room 125	8/13/2014	0.247	0.113		P		8/22/2017	0.03	0.021		P		P	None
17	B	hallway outside custodial 127, left	8/13/2014	0.106	0.098		P		8/22/2017	0.096	0.118		P		P	None
18	B	hallway outside custodial 127, right	8/13/2014	0.12	0.101		P		8/22/2017	0.099	0.061		P		P	None
19	S/B	classroom 129	8/13/2014	0.278	0.219		P		8/22/2017	0.164	0.142		P		P	None
20	S/B	classroom 201	8/13/2014	0.099	0.092		P		8/22/2017	0.211	0.204		P		P	None
21	S/B	classroom 203	8/13/2014	0.084	0.112		P		8/22/2017	0.17	0.135		P		P	None
22	S/B	work room 204C	8/13/2014	0.19	0.176		P		8/22/2017	0.153	0.106		P		P	None
23	S/B	library 205	8/13/2014	0.123	0.187		P		8/22/2017	0.173	0.213		P		P	None
24	S/B	classroom 206	8/13/2014	0.178	0.121		P		8/22/2017	0.183	0.108		P		P	None
25	S/B	classroom 208	8/13/2014	0.233	0.105		P		8/22/2017	0.177	0.257		P		P	None
26	S/B	classroom 210	8/13/2014	0.212	0.094		P		8/22/2017	0.098	0.034		P		P	None
27	B	hallway, outside 210, left	8/13/2014	0.106	0.094		P		8/22/2017	0.194	0.032		P		P	None
28	B	hallway, outside 210, right	8/13/2014	0.204	0.092		P		8/22/2017	0.09	0.035		P		P	None
29	S/B	classroom 216	8/13/2014	0.113	0.09		P		8/22/2017	0.085	0.045		P		P	None
30	S/B	classroom 217	8/13/2014	0.157	0.195		P		8/22/2017	0.25	0.306		P		P	None
31	S/B	classroom 218	8/13/2014	0.142	0.168		P		8/22/2017	0.237	0.24		P		P	None
32	S/B	classroom 219	8/13/2014	0.135	0.158		P		8/22/2017	0.269	0.235		P		P	None
33	S/B	kindergarten, 220	8/13/2014	0.261	0.222		P		8/22/2017	0.2	0.203		P		P	None
34	B	hallway, outside kindergarten, left	8/13/2014	0.235	0.19		P		8/22/2017	0.219	0.182		P		P	None
35	B	hallway, outside kindergarten, right	8/13/2014	0.228	0.16		P		8/22/2017	0.222	0.168		P		P	None
36	S/B	kindergarten, 221	8/13/2014	0.19	0.181		P		8/22/2017	0.188	0.194		P		P	None
37	B	kindergarten, 222	8/13/2014	0.223	0.204		P		8/22/2017	0.197	0.226		P		P	None
38	S/B	OT/PT 224	8/13/2014	0.192	0.177		P		8/22/2017	0.145	0.19		P		P	None
39	S/B	Special Ed. 226	8/13/2014	0.193	0.151		P		8/22/2017	0.177	0.151		P		P	None
40	S/B	special Ed. 227	8/13/2014	0.187	0.145		P		8/22/2017	0.161	0.179		P		P	None
41	B	hallway, outside 227, left	8/13/2014	0.156	0.126		P		8/22/2017	0.174	0.18		P		P	None
42	B	hallway, outside 227, right	8/13/2014	0.15	0.114		P		8/22/2017	0.155	0.17		P		P	None
43	S/B	classroom 300	8/13/2014	0.188	0.213		P		8/22/2017	0.192	0.203		P		P	None
44	B	hallway, outside 301, left	8/13/2014	0.235	0.152		P		8/22/2017	0.229	0.187		P		P	None
45	B	hallway, outside 301, right	8/13/2014	0.265	0.18		P		8/22/2017	0.214	0.215		P		P	None
46	S/B	classroom 301	8/13/2014	0.181	0.229		P		8/22/2017	0.196	0.22		P		P	None
47	S/B	classroom 302	8/13/2014	0.582	0.267		P		8/22/2017	0.255	0.203		P		P	None
48	S/B	classroom 303	8/13/2014	0.194	0.182		P		8/22/2017	0.155	0.17		P		P	None
49	S/B	classroom 304	8/13/2014	0.185	0.248		P		8/22/2017	0.15	0.207		P		P	None
50	S	classroom 305	8/13/2014	0.223	0.155		P		8/22/2017	0.212	0.213		P		P	None

Table 5. Iron Test Results

Test Results (Iron/Fe, ppm)																
FIXTURE INFORMATION			Initial Sampling						Follow-up Sampling 1						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	B	Entry hallway, left 01	8/13/2014			<0.05	P								P	None
02	B	Entry hallway, right 01							8/22/2017			<0.05	P		P	None
13	B	gym, bottle filler 05	8/13/2014			<0.05	P								P	None
14	S	nurse office 111	8/13/2014			<0.05	P								P	None
15	S	work room 113							8/22/2017			<0.05	P		P	None
16	S	family room 125							8/22/2017			<0.05	P		P	None
19	S/B	classroom 129	8/13/2014			<0.05	P								P	None
20	S/B	classroom 201	8/13/2014			<0.05	P								P	None
21	S/B	classroom 203							8/22/2017			<0.05	P		P	None
22	S/B	work room 204C							8/22/2017			<0.05	P		P	None
32	S/B	classroom 219	8/13/2014			<0.05	P								P	None
33	S/B	kindergarten, 220	8/13/2014			<0.05	P								P	None
34	B	hallway, outside kindergarten, left							8/22/2017			<0.05	P		P	None
35	B	hallway, outside kindergarten, right							8/22/2017			<0.05	P		P	None
43	S/B	classroom 300	8/13/2014			<0.05	P								P	None
44	B	hallway, outside 301, left							8/22/2017			<0.05	P		P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room	Arsenic	22-Aug-17	2 ppb	P
00	SE	boiler room	Cadmium	22-Aug-17	1 ppb	P
00	SE	boiler room	Copper	22-Aug-17	0.007 ppm	P
00	SE	boiler room	Iron	22-Aug-17	<0.05 ppm	P
00	SE	boiler room	Lead	22-Aug-17	1 ppb	P
00	SE	boiler room	Total Coliforms	13-Aug-14	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).
 "n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.