

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Garfield High School

Updated April 30, 2018

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria: There is one location that does not meet the policy criteria. A sign will be posted at room 219, band room (#139)

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
101	B	first floor, hallway by 103,	P	None	P	None	P	None	P	None	Yes
102	B	first floor, hallway by 103, bottle filler	P	None	P	None	P	None			Yes
103	S	room 105	P	None	P	None	P	None			Yes
104	S	room 106, west wall, right	P	None	P	None	P	None			Yes
105	S	room 106, west wall, middle	P	None	P	None	P	None			Yes
106	S	room 106, west wall, left	P	None	P	None	P	None			Yes
107	S	room 106, south wall	P	None	P	None	P	None			Yes
108	S	room 106, east wall, south end, right	P	None	P	None	P	None			Yes
109	S	room 106, east wall, south end, middle	P	None	P	None	P	None	P	None	Yes
110	S	room 106, east wall, south end, left	P	None	P	None	P	None			Yes
111	Sp	room 106, east wall, north, right	P	None	P	None	P	None			Yes
112	S	room 106, east wall, north, left	P	None	P	None	P	None			Yes
113	B	commons, 100,	P	None	P	None	P	None			Yes
114	B	commons, 100, bottle filler	P	None	P	None	P	None	P	None	Yes
115	S	Kitchen, east-north	P	None	P	None	P	None			Yes
116	S	Kitchen, East, left	P	None	P	None	P	None	P	None	Yes
117	Sp	Kitchen, East, right	P	None	P	None	P	None			Yes
118	K	Kitchen, Kettle	P	None	P	None	P	None			Yes
119	S	kitchen, middle	P	None	P	None	P	None			Yes
120	S	workroom 108	P	None	P	None	P	None			Yes
121	S	Kitchen, West wall, right	P	None	P	None	P	None			Yes
122	S	first floor, staff lounge, 109	P	None	P	None	P	None	P	None	Yes
123	S	custodian break room	P	None	P	None	P	None	P	None	Yes
124	S	room 119, student store	P	None	P	None	P	None			Yes
125	S	room 200C, library office	P	None	P	None	P	None			Yes
126	S	room 237	P	None	P	None	P	None	P	None	Yes
127	S	room 239	P	None	P	None	P	None			Yes
128	S	room 244	P	None	P	None	P	None			Yes
129	B	2nd floor, hallway by staff women restroom, left	P	None	P	None	P	None			Yes
130	B	2nd floor, hallway by staff women restroom, right	P	None	P	None	P	None	P	None	Yes
131	S	room 211	P	None	P	None	P	None	P	None	Yes
132	S	room 213	P	None	P	None	P	None	P	None	Yes
133	S	staff conference room	P	None	P	None	P	None			Yes
134	S	room 215	P	None	P	None	P	None			Yes
135	S	room 216	P	None	P	None	P	None			Yes
136	B	2nd floor, hallway, cross from room 218, left	P	None	P	None	P	None			Yes
137	B	2nd floor, hallway, cross from room 217.right	P	None	P	None	P	None			Yes
138	B/S	room 217, Jazz, choir room	P	None	P	None	P	None			Yes
139	S	room 219, band room	P	None	P	None	F	PS	P	None	PS
140	S	room 228	P	None	P	None	P	None	P	None	Yes
141	S	room 230	P	None	P	None	P	None	P	None	Yes
143	S	room 236	P	None	P	None	P	None	P	None	Yes
144	B	3rd floor, by staff women restroom, left	P	None	P	None	P	None			Yes
145	B	3rd floor, by staff women restroom, right	P	None	P	None	P	None	P	None	Yes
152	S	staff conference	P	None	P	None	P	None	P	None	Yes
153	S	room 326, east	P	None	P	None	P	None			Yes

154	S	room 326, south, left	P	None	P	None	P	None			Yes
155	S	room 326, south, right	P	None	P	None	P	None	P	None	Yes
156	S	room 331 staff conference	P	None	P	None	P	None	P	None	Yes
157	S	first floor, conference room	P	None	P	None	P	None			Yes
158	S	nurse office, 102A	P	None	P	None	P	None			Yes
159	S	nurse office, 102E	P	None	P	None	P	None			Yes
160	S	nurse office, 102F	P	None	P	None	P	None			Yes
161	S	nurse office, 102H	P	None	P	None	P	None	P	None	Yes
162	S	main office, work room, room 101E	P	None	P	None	P	None	P	None	Yes
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	P	None	P	None	P	None			Yes
169	S	room 120	P	None	P	None	P	None			Yes
170	S	Gym first floor, training room 131	P	None	P	None	P	None	P	None	Yes
171	B	Gym first floor,, men's locker room	P	None	P	None	P	None	P	None	Yes
172	B	Gym first floor, women's locker room	P	None	P	None	P	None			Yes
173	B	Gym first floor, weight room 125	P	None	P	None	P	None	P	None	Yes
174	B	Gym first floor, hallway, left	P	None	P	None	P	None			Yes
175	B	Gym first floor, hallway, right	P	None	P	None	P	None	P	None	Yes
176	S	concession 112	P	None	P	None	P	None			Yes
177	S	counselor center, work room, 104	P	None	P	None	P	None	P	None	Yes
178	B	outside auditorium, left	P	None	P	None	P	None			Yes
179	B	outside auditorium, right	P	None	P	None	P	None			Yes
180	S	Gym, second floor, concessions	P	None	P	None	P	None	P	None	Yes
181	B	Gym, second floor, hallway, left	P	None	P	None	P	None	P	None	Yes
182	B	Gym, second floor, hallway, middle	P	None	P	None	P	None			Yes
183	B	Gym, second floor, hallway, right	P	None	P	None	P	None			Yes
186	B	3rd floor, hallway, outside 317, left	P	None	P	None	P	None			Yes
187	B	3rd floor, hallway, outside 317, right	P	None	P	None	P	None			Yes
188	S	room 106, middle sink	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
101	B	first floor, hallway by 103,	8/28/2008	4	1	P													8/9/2011	4	2	P
102	B	first floor, hallway by 103, bottle filler	8/28/2008	3	3	P													8/9/2011	3	2	P
103	S	room 105	8/28/2008	12	6		9/9/2008	6	1	P									8/9/2011	3	<1	P
104	S	room 106, west wall, right	8/28/2008	11	7						9/19/2008	16	7						8/9/2011	3	<1	P
105	S	room 106, west wall, middle	8/28/2008	12	8		9/9/2008	4	1	P									8/9/2011	2	<1	P
106	S	room 106, west wall, left	8/28/2008	10	3	P													8/9/2011	3	2	P
107	S	room 106, south wall	8/28/2008	10	8	P													8/9/2011	4	<1	P
108	S	room 106, east wall, south end, right	8/28/2008	10	8	P													8/9/2011	4	<1	P
109	S	room 106, east wall, south end, middle	8/28/2008	10	8	P													8/9/2011	4	<1	P
110	S	room 106, east wall, south end, left	8/28/2008	11	8		9/9/2008	4	<1	P									8/9/2011	4	<1	P
111	Sp	room 106, east wall, north, right	8/28/2008	43	12		9/9/2008	7	4	P									8/9/2011	9	<1	P
112	S	room 106, east wall, north, left	8/28/2008	12	9		9/9/2008	23	12										8/9/2011	4	1	P
113	B	commons, 100,	8/28/2008	8	7	P													8/9/2011	3	<1	P
114	B	commons, 100, bottle filler																				
115	S	Kitchen, east-north	8/28/2008	8	<1	P													8/9/2011	1	<1	P
116	S	Kitchen, East, left	8/28/2008	16	3		9/9/2008	8	<1	P									8/9/2011	4	<1	P
117	Sp	Kitchen, East, right	8/28/2008	121	15		9/9/2008	25	4										8/9/2011	18	<1	
118	K	Kitchen, Kettle	8/28/2008	89	5		9/9/2008	141	4					11/7/2008	3	1	P		8/9/2011	5	2	P
119	S	kitchen, middle	8/28/2008	9	1	P													8/9/2011	<1	<1	P
120	S	workroom 108	8/28/2008	60	4		9/9/2008	30	12										8/9/2011	4	1	P
121	S	Kitchen, West wall, right	8/28/2008	19	1		9/9/2008	18	1										8/9/2011	<1	<1	P
122	S	first floor, staff lounge, 109	8/28/2008	7	5	P													8/9/2011	4	<1	P
123	S	custodian break room	8/28/2008	7	4	P													8/9/2011	<1	<1	P
124	S	room 119, student store	8/28/2008	7	4	P													8/9/2011	8	<1	P
125	S	room 200C, library office	8/28/2008	7	27		9/9/2008	5	<1	P									8/9/2011	<1	<1	P
126	S	room 237	8/28/2008	1	7	P													8/9/2011	2	<1	P
127	S	room 239	8/28/2008	5	2	P													8/9/2011	4	<1	P
128	S	room 244	8/28/2008	2	<1	P													8/9/2011	3	<1	P
129	B	2nd floor, hallway by staff women restroom, left	8/28/2008	2	<1	P													8/9/2011	<1	<1	P
130	B	2nd floor, hallway by staff women restroom, right	8/28/2008	2	2	P													8/9/2011	<1	<1	P
131	S	room 211	8/28/2008	<1	<1	P													8/9/2011	<1	<1	P
132	S	room 213	8/28/2008	5	1	P													8/9/2011	7	1	P
133	S	staff conference room	8/28/2008	7	1	P													8/9/2011	5	<1	P
134	S	room 215	8/28/2008	11	14		9/9/2008	7	2	P									8/9/2011	6	4	P
135	S	room 216	8/28/2008	11	12		9/9/2008	7	2	P									8/9/2011	7	1	P
136	B	2nd floor, hallway, cross from room 218, left									9/19/2008	4	3	P					8/9/2011	2	<1	P
137	B	2nd floor, hallway, cross from room 217, right									9/19/2008	3	3	P					8/9/2011	1	<1	P
138	B/S	room 217, Jazz, choir room	8/28/2008	15	4		9/9/2008	9	2	P									8/9/2011	4	1	P
139	S	room 219, band room	8/28/2008	8	6	P																
140	S	room 228	8/28/2008	6	2	P													8/9/2011	3	<1	P
141	S	room 230	8/28/2008	4	2	P													8/9/2011	<1	<1	P
143	S	room 236	8/28/2008	2	1	P													8/9/2011	7	2	P
144	B	3rd floor, by staff women restroom, left	8/28/2008	1	<1	P													8/9/2011	2	<1	P
145	B	3rd floor, by staff women restroom, right	8/28/2008	<1	<1	P													8/9/2011	1	<1	P
152	S	starff conference	8/28/2008	5	<1	P													8/9/2011	3	<1	P
153	S	room 326, east	8/28/2008	5	<1	P													8/9/2011	7	<1	P
154	S	room 326, south, left	8/28/2008	<1	<1	P													8/9/2011	4	<1	P

155	S	room 326, south, right	8/28/2008	10	<1	P												8/9/2011	5	<1	P	
156	S	room 331 staff conference									9/19/2008	3	4	P					8/9/2011	6	2	P
157	S	first floor, conference room	8/28/2008	11	<1		9/9/2008	11	2										8/9/2011	4	<1	P
158	S	nurse office, 102A	8/28/2008	9	2	P													8/9/2011	4	<1	P
159	S	nurse office, 102E	8/28/2008	3	<1	P													8/9/2011	4	<1	P
160	S	nurse office, 102F	8/28/2008	9	1	P													8/9/2011	3	2	P
161	S	nurse office, 102H	8/28/2008	9	13		9/9/2008	8	1	P									8/9/2011	7	2	P
162	S	main office, work room, room 101E	8/28/2008	<1	1	P													8/9/2011	3	<1	P
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	8/28/2008	28	2		9/9/2008	25	1										8/9/2011	6	<1	P
169	S	room 120	8/28/2008	6	4	P													8/9/2011	2	<1	P
170	S	Gym first floor, training room 131					9/9/2008	18	4										8/9/2011	4	1	P
171	B	Gym first floor,, men's locker room					9/9/2008	4	4	P									8/9/2011	2	2	P
172	B	Gym first floor, women's locker room																	8/9/2011	7	1	P
173	B	Gym first floor, weight room 125					9/9/2008	4	8	P									8/9/2011	<1	<1	P
174	B	Gym first floor, hallway, left					9/9/2008	3	4	P									8/9/2011	<1	2	P
175	B	Gym first floor, hallway, right					9/9/2008	3	4	P									8/9/2011	3	2	P
176	S	concession 112																				
177	S	counselor center, work room, 104					9/9/2008	5	2	P									8/9/2011	4	<1	P
178	B	outside auditorium, left																				
179	B	outside auditorium, right																				
180	S	Gym, second floor, concessions									9/19/2008	16	2						8/9/2011	6	2	P
181	B	Gym, second floor, hallway, left					9/9/2008	2	3	P									8/9/2011	1	1	P
182	B	Gym, second floor, hallway, middle					9/9/2008	2	3	P									8/9/2011	1	1	P
183	B	Gym, second floor, hallway, right					9/9/2008	3	3	P									8/9/2011	1	2	P
186	B	3rd floor, hallway, outside 317, left									9/19/2008	4	3	P					8/9/2011	2	<1	P
187	B	3rd floor, hallway, outside 317, right									9/19/2008	<1	1	P					8/9/2011	2	<1	P
188	S	room 106, middle sink																				

Table 2. Lead Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Follow-up Sampling 8				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass/ Fail	Pass/Fail	Status
101	B	first floor, hallway by 103,	7/11/2014	1	<1	P									4/11/2018	<1	<1	P	P	None
102	B	first floor, hallway by 103, bottle filler	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
103	S	room 105													4/11/2018	<1	<1	P	P	None
104	S	room 106, west wall, right	7/11/2014	2	<1	P									4/11/2018	<1	<1	P	P	None
105	S	room 106, west wall, middle	7/11/2014	1	<1	P									4/11/2018	<1	<1	P	P	None
106	S	room 106, west wall, left	7/11/2014	5	<1	P									4/11/2018	<1	<1	P	P	None
107	S	room 106, south wall	7/11/2014	4	<1	P									4/11/2018	<1	1	P	P	None
108	S	room 106, east wall, south end, right	7/11/2014	2	<1	P									4/11/2018	2	<1	P	P	None
109	S	room 106, east wall, south end, middle	7/11/2014	<1	<1	P									4/11/2018	7	<1	P	P	None
110	S	room 106, east wall, south end, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
111	Sp	room 106, east wall, north, right	7/11/2014	5	<1	P													P	None
112	S	room 106, east wall, north, left													4/11/2018	9	1	P	P	None
113	B	commons, 100,	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
114	B	commons, 100, bottle filler					1/15/2016	<1	<1	P	2/8/2016	<1	<1	P	4/11/2018	<1	<1	P	P	None
115	S	Kitchen, east-north	7/11/2014	<1	<1	P									4/11/2018	2	<1	P	P	None
116	S	Kitchen, East, left	7/11/2014	4	<1	P									4/11/2018	1	<1	P	P	None
117	Sp	Kitchen, East, right	7/11/2014	1	<1	P									4/11/2018	1	<1	P	P	None
118	K	Kitchen, Kettle	7/11/2014	3	<1	P									4/11/2018	1	<1	P	P	None
119	S	kitchen, middle	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
120	S	workroom 108	7/11/2014	2	<1	P									4/11/2018	1	<1	P	P	None
121	S	Kitchen, West wall, right	7/11/2014	1	<1	P									4/11/2018	1	<1	P	P	None
122	S	first floor, staff lounge, 109	7/11/2014	3	<1	P									4/11/2018	<1	<1	P	P	None
123	S	custodian break room	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
124	S	room 119, student store																	P	None
125	S	room 200C, library office	7/11/2014	4	<1	P									4/11/2018	1	<1	P	P	None
126	S	room 237	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
127	S	room 239	7/11/2014	4	<1	P									4/11/2018	<1	<1	P	P	None
128	S	room 244	7/11/2014	4	<1	P									4/11/2018	<1	<1	P	P	None
129	B	2nd floor, hallway by staff women restroom, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
130	B	2nd floor, hallway by staff women restroom, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
131	S	room 211	7/11/2014	4	<1	P									4/11/2018	2	<1	P	P	None
132	S	room 213													4/11/2018	2	<1	P	P	None
133	S	staff conference room	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
134	S	room 215	7/11/2014	2	<1	P									4/11/2018	<1	<1	P	P	None
135	S	room 216	7/11/2014	3	1	P									4/11/2018	1	<1	P	P	None
136	B	2nd floor, hallway, cross from room 218, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
137	B	2nd floor, hallway, cross from room 217, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
138	B/S	room 217, Jazz, choir room	7/11/2014	2	<1	P									4/11/2018	1	<1	P	P	None
139	S	room 219, band room	7/11/2014	6	<1	P									4/11/2018	<1	<1	P	P	None
140	S	room 228	7/11/2014	3	<1	P									4/11/2018	2	<1	P	P	None
141	S	room 230	7/11/2014	6	<1	P									4/11/2018	3	<1	P	P	None
143	S	room 236	7/11/2014	6	<1	P									4/11/2018	2	<1	P	P	None
144	B	3rd floor, by staff women restroom, left	7/11/2014	1	<1	P									4/11/2018	<1	<1	P	P	None
145	B	3rd floor, by staff women restroom, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
152	S	starff conference	7/11/2014	3	<1	P									4/11/2018	1	<1	P	P	None
153	S	room 326, east	7/11/2014	8	<1	P									4/11/2018	2	<1	P	P	None

154	S	room 326, south, left	7/11/2014	2	<1	P								4/11/2018	<1	<1	P	P	None
155	S	room 326, south, right	7/11/2014	5	<1	P								4/11/2018	<1	<1	P	P	None
156	S	room 331 staff conference	7/11/2014	5	<1	P								4/11/2018	<1		P	P	None
157	S	first floor, conference room	7/11/2014	6	<1	P								4/11/2018	2	<1	P	P	None
158	S	nurse office, 102A	7/11/2014	3	<1	P								4/11/2018	1	<1	P	P	None
159	S	nurse office, 102E	7/11/2014	3	<1	P								4/11/2018	2	<1	P	P	None
160	S	nurse office, 102F	7/11/2014	3	<1	P								4/11/2018	2	<1	P	P	None
161	S	nurse office, 102H	7/11/2014	7	<1	P								4/11/2018	4	<1	P	P	None
162	S	main office, work room, room 101E	7/11/2014	2	<1	P								4/11/2018	2	<1	P	P	None
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	7/11/2014	4	<1	P								4/11/2018	<1	<1	P	P	None
169	S	room 120	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
170	S	Gym first floor, training room 131	7/11/2014	<1	<1	P								4/11/2018	1	<1	P	P	None
171	B	Gym first floor,, men's locker room	7/11/2014	<1	1	P								4/11/2018	<1	<1	P	P	None
172	B	Gym first floor, women's locker room	7/11/2014	3	<1	P								4/11/2018	<1	<1	P	P	None
173	B	Gym first floor, weight room 125	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
174	B	Gym first floor, hallway, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
175	B	Gym first floor, hallway, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
176	S	concession 112	7/11/2014	2	<1	P												P	None
177	S	counselor center, work room, 104	7/11/2014	2	<1	P								4/11/2018	<1	<1	P	P	None
178	B	outside auditorium, left												4/11/2018	<1	<1	P	P	None
179	B	outside auditorium, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
180	S	Gym, second floor, concessions	7/11/2014	2	1	P												P	None
181	B	Gym, second floor, hallway, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
182	B	Gym, second floor, hallway, middle	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
183	B	Gym, second floor, hallway, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
186	B	3rd floor, hallway, outside 317, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
187	B	3rd floor, hallway, outside 317, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
188	S	room 106, middle sink	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
101	B	first floor, hallway by 103,	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
102	B	first floor, hallway by 103, bottle filler	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
103	S	room 105	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
104	S	room 106, west wall, right	8/28/2008	<1	<1	P					9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
105	S	room 106, west wall, middle	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
106	S	room 106, west wall, left	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
107	S	room 106, south wall	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
108	S	room 106, east wall, south end, right	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
109	S	room 106, east wall, south end, middle	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
110	S	room 106, east wall, south end, left	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
111	Sp	room 106, east wall, north, right	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
112	S	room 106, east wall, north, left	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
113	B	commons, 100,	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
114	B	commons, 100, bottle filler																
115	S	Kitchen, east-north	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
116	S	Kitchen, East, left	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
117	Sp	Kitchen, East, right	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
118	K	Kitchen, Kettle	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
119	S	kitchen, middle	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
120	S	workroom 108	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
121	S	Kitchen, West wall, right	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
122	S	first floor, staff lounge, 109	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
123	S	custodian break room	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
124	S	room 119, student store	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
125	S	room 200C, library office	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
126	S	room 237	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
127	S	room 239	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
128	S	room 244	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
129	B	2nd floor, hallway by staff women restroom, left	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
130	B	2nd floor, hallway by staff women restroom, right	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
131	S	room 211	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
132	S	room 213	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
133	S	staff conference room	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
134	S	room 215	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
135	S	room 216	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
136	B	2nd floor, hallway, cross from room 218, left									9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
137	B	2nd floor, hallway, cross from room 217.right									9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
138	B/S	room 217, Jazz, choir room	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P					8/9/2011	<1	<1	P
139	S	room 219, band room	8/28/2008	<1	<1	P												
140	S	room 228	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
141	S	room 230	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
143	S	room 236	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
144	B	3rd floor, by staff women restroom, left	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
145	B	3rd floor, by staff women restroom, right	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
152	S	starff conference	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
153	S	room 326, east	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P
154	S	room 326, south, left	8/28/2008	<1	<1	P									8/9/2011	<1	<1	P

155	S	room 326, south, right	8/28/2008	<1	<1	P								8/9/2011	<1	<1	P	
156	S	room 331 staff conference									9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
157	S	first floor, conference room	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
158	S	nurse office, 102A	8/28/2008	<1	<1	P								8/9/2011	<1	<1	P	
159	S	nurse office, 102E	8/28/2008	<1	<1	P								8/9/2011	<1	<1	P	
160	S	nurse office, 102F	8/28/2008	<1	<1	P								8/9/2011	<1	<1	P	
161	S	nurse office, 102H	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
162	S	main office, work room, room 101E	8/28/2008	<1	<1	P								8/9/2011	<1	<1	P	
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	8/28/2008	<1	<1	P	9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
169	S	room 120	8/28/2008	<1	<1	P								8/9/2011	<1	<1	P	
170	S	Gym first floor, training room 131					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
171	B	Gym first floor,, men's locker room					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
172	B	Gym first floor, women's locker room												8/9/2011	<1	<1	P	
173	B	Gym first floor, weight room 125					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
174	B	Gym first floor, hallway, left					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
175	B	Gym first floor, hallway, right					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
176	S	concession 112																
177	S	counselor center, work room, 104					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
178	B	outside auditorium, left																
179	B	outside auditorium, right																
180	S	Gym, second floor, concessions									9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
181	B	Gym, second floor, hallway, left					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
182	B	Gym, second floor, hallway, middle					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
183	B	Gym, second floor, hallway, right					9/9/2008	<1	<1	P				8/9/2011	<1	<1	P	
186	B	3rd floor, hallway, outside 317, left									9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
187	B	3rd floor, hallway, outside 317, right									9/19/2008	<1	<1	P	8/9/2011	<1	<1	P
188	S	room 106, middle sink																

Table 3. Cadmium Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
101	B	first floor, hallway by 103,	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
102	B	first floor, hallway by 103, bottle filler	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
103	S	room 105													4/11/2018	<1	<1	P	P	None
104	S	room 106, west wall, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
105	S	room 106, west wall, middle	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
106	S	room 106, west wall, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
107	S	room 106, south wall	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
108	S	room 106, east wall, south end, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
109	S	room 106, east wall, south end, middle	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
110	S	room 106, east wall, south end, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
111	Sp	room 106, east wall, north, right	7/11/2014	<1	<1	P													P	None
112	S	room 106, east wall, north, left													4/11/2018	<1	<1	P	P	None
113	B	commons, 100,	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
114	B	commons, 100, bottle filler					1/15/2016	<1	<1	P	2/8/2016	<1	<1	P	4/11/2018	<1	<1	P	P	None
115	S	Kitchen, east-north	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
116	S	Kitchen, East, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
117	Sp	Kitchen, East, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
118	K	Kitchen, Kettle	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
119	S	kitchen, middle	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
120	S	workroom 108	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
121	S	Kitchen, West wall, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
122	S	first floor, staff lounge, 109	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
123	S	custodian break room	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
124	S	room 119, student store																	P	None
125	S	room 200C, library office	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
126	S	room 237	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
127	S	room 239	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
128	S	room 244	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
129	B	2nd floor, hallway by staff women restroom, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
130	B	2nd floor, hallway by staff women restroom, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
131	S	room 211	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
132	S	room 213													4/11/2018	<1	<1	P	P	None
133	S	staff conference room	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
134	S	room 215	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
135	S	room 216	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
136	B	2nd floor, hallway, cross from room 218, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
137	B	2nd floor, hallway, cross from room 217, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
138	B/S	room 217, Jazz, choir room	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
139	S	room 219, band room	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
140	S	room 228	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
141	S	room 230	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
143	S	room 236	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
144	B	3rd floor, by staff women restroom, left	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
145	B	3rd floor, by staff women restroom, right	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
152	S	starff conference	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None
153	S	room 326, east	7/11/2014	<1	<1	P									4/11/2018	<1	<1	P	P	None

154	S	room 326, south, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
155	S	room 326, south, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
156	S	room 331 staff conference	7/11/2014	<1	<1	P								4/11/2018	<1		P	P	None
157	S	first floor, conference room	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
158	S	nurse office, 102A	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
159	S	nurse office, 102E	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
160	S	nurse office, 102F	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
161	S	nurse office, 102H	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
162	S	main office, work room, room 101E	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
169	S	room 120	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
170	S	Gym first floor, training room 131	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
171	B	Gym first floor,, men's locker room	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
172	B	Gym first floor, women's locker room	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
173	B	Gym first floor, weight room 125	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
174	B	Gym first floor, hallway, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
175	B	Gym first floor, hallway, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
176	S	concession 112	7/11/2014	<1	<1	P												P	None
177	S	counselor center, work room, 104	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
178	B	outside auditorium, left												4/11/2018	<1	<1	P	P	None
179	B	outside auditorium, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
180	S	Gym, second floor, concessions	7/11/2014	<1	<1	P												P	None
181	B	Gym, second floor, hallway, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
182	B	Gym, second floor, hallway, middle	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
183	B	Gym, second floor, hallway, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
186	B	3rd floor, hallway, outside 317, left	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
187	B	3rd floor, hallway, outside 317, right	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None
188	S	room 106, middle sink	7/11/2014	<1	<1	P								4/11/2018	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
101	B	first floor, hallway by 103,	8/28/2008	0.519	0.239	P									8/9/2011	0.283	0.174	P
102	B	first floor, hallway by 103, bottle filler	8/28/2008	0.318	0.153	P									8/9/2011	0.271	0.188	P
103	S	room 105	8/28/2008	0.329	0.318	P	9/9/2008	0.317	0.258	P					8/9/2011	0.24	0.273	P
104	S	room 106, west wall, right	8/28/2008	0.254	0.266	P					9/19/2008	0.762	0.381	P	8/9/2011	0.292	0.109	P
105	S	room 106, west wall, middle	8/28/2008	0.226	0.253	P	9/9/2008	0.278	0.339	P					8/9/2011	0.303	0.104	P
106	S	room 106, west wall, left	8/28/2008	0.262	0.178	P									8/9/2011	0.113	0.096	P
107	S	room 106, south wall	8/28/2008	0.226	0.22	P									8/9/2011	0.236	0.101	P
108	S	room 106, east wall, south end, right	8/28/2008	0.228	0.218	P									8/9/2011	0.219	0.114	P
109	S	room 106, east wall, south end, middle	8/28/2008	0.233	0.227	P									8/9/2011	0.231	0.174	P
110	S	room 106, east wall, south end, left	8/28/2008	0.257	0.233	P	9/9/2008	0.281	0.265	P					8/9/2011	0.28	0.178	P
111	Sp	room 106, east wall, north, right	8/28/2008	0.615	0.328	P	9/9/2008	0.836	0.335	P					8/9/2011	0.211	0.245	P
112	S	room 106, east wall, north, left	8/28/2008	0.204	0.236	P	9/9/2008	0.289	0.351	P					8/9/2011	0.184	0.376	P
113	B	commons, 100,	8/28/2008	0.278	0.278	P									8/9/2011	0.215	0.112	P
114	B	commons, 100, bottle filler																
115	S	Kitchen, east-north	8/28/2008	0.262	0.193	P									8/9/2011	0.29	0.07	P
116	S	Kitchen, East, left	8/28/2008	0.221	0.23	P	9/9/2008	0.231	0.222	P					8/9/2011	0.357	0.077	P
117	Sp	Kitchen, East, right	8/28/2008	3.72	0.778		9/9/2008	0.317	0.366	P					8/9/2011	0.471	0.057	P
118	K	Kitchen, Kettle	8/28/2008	0.297	0.093	P	9/9/2008	0.28	0.323	P					8/9/2011	0.518	0.332	P
119	S	kitchen, middle	8/28/2008	0.18	0.26	P									8/9/2011	0.245	0.251	P
120	S	workroom 108	8/28/2008	0.268	0.272	P	9/9/2008	0.247	0.233	P					8/9/2011	0.203	0.223	P
121	S	Kitchen, West wall, right	8/28/2008	0.14	0.262	P	9/9/2008	0.221	0.378	P					8/9/2011	0.224	0.287	P
122	S	first floor, staff lounge, 109	8/28/2008	0.201	0.256	P									8/9/2011	0.229	0.134	P
123	S	custodian break room	8/28/2008	0.298	0.388	P									8/9/2011	0.119	0.114	P
124	S	room 119, student store	8/28/2008	0.314	0.307	P									8/9/2011	0.361	0.274	P
125	S	room 200C, library office	8/28/2008	0.324	0.184	P	9/9/2008	0.344	0.258	P					8/9/2011	0.078	0.085	P
126	S	room 237	8/28/2008	0.241	0.236	P									8/9/2011	0.292	0.313	P
127	S	room 239	8/28/2008	0.316	0.35	P									8/9/2011	0.259	0.418	P
128	S	room 244	8/28/2008	0.273	0.333	P									8/9/2011	0.317	0.306	P
129	B	2nd floor, hallway by staff women restroom, left	8/28/2008	0.321	0.219	P									8/9/2011	0.3	0.202	P
130	B	2nd floor, hallway by staff women restroom, right	8/28/2008	0.244	0.219	P									8/9/2011	0.258	0.194	P
131	S	room 211	8/28/2008	0.325	0.177	P									8/9/2011	0.079	0.079	P
132	S	room 213	8/28/2008	0.369	0.168	P									8/9/2011	0.255	0.29	P
133	S	staff conference room	8/28/2008	0.285	0.183	P									8/9/2011	0.23	0.158	P
134	S	room 215	8/28/2008	0.31	0.233	P	9/9/2008	0.375	0.244	P					8/9/2011	0.281	0.256	P
135	S	room 216	8/28/2008	0.379	0.284	P	9/9/2008	0.33	0.246	P					8/9/2011	0.261	0.262	P
136	B	2nd floor, hallway, cross from room 218, left									9/19/2008	0.255	0.205	P	8/9/2011	0.346	0.338	P
137	B	2nd floor, hallway, cross from room 217.right									9/19/2008	0.196	0.195	P	8/9/2011	0.373	0.316	P
138	B/S	room 217, Jazz, choir room	8/28/2008	0.408	0.415	P	9/9/2008	0.462	0.401	P					8/9/2011	0.358	0.286	P
139	S	room 219, band room	8/28/2008	0.389	0.437	P												
140	S	room 228	8/28/2008	0.273	0.353	P									8/9/2011	0.225	0.318	P
141	S	room 230	8/28/2008	0.235	0.22	P									8/9/2011	0.052	0.052	P
143	S	room 236	8/28/2008	0.404	0.191	P									8/9/2011	0.282	0.219	P
144	B	3rd floor, by staff women restroom, left	8/28/2008	0.346	0.166	P									8/9/2011	0.397	0.255	P
145	B	3rd floor, by staff women restroom, right	8/28/2008	0.208	0.198	P									8/9/2011	0.227	0.186	P
152	S	starff conference	8/28/2008	0.429	0.178	P									8/9/2011	0.307	0.078	P
153	S	room 326, east	8/28/2008	0.264	0.275	P									8/9/2011	0.245	0.098	P
154	S	room 326, south, left	8/28/2008	0.261	0.182	P									8/9/2011	0.215	0.115	P

155	S	room 326, south, right	8/28/2008	0.317	0.176	P								8/9/2011	0.227	0.176	P	
156	S	room 331 staff conference									9/19/2008	0.248	0.212	P	8/9/2011	0.403	0.384	P
157	S	first floor, conference room	8/28/2008	0.345	0.883	P	9/9/2008	0.531	1.67					8/9/2011	0.267	0.24	P	
158	S	nurse office, 102A	8/28/2008	0.242	0.332	P								8/9/2011	0.304	0.319	P	
159	S	nurse office, 102E	8/28/2008	0.173	0.271	P								8/9/2011	0.202	0.274	P	
160	S	nurse office, 102F	8/28/2008	0.177	0.187	P								8/9/2011	0.163	0.204	P	
161	S	nurse office, 102H	8/28/2008	0.253	0.15	P	9/9/2008	0.229	0.24	P				8/9/2011	0.202	0.177	P	
162	S	main office, work room, room 101E	8/28/2008	0.376	0.496	P								8/9/2011	0.246	0.276	P	
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	8/28/2008	0.258	0.29	P	9/9/2008	0.303	0.283	P				8/9/2011	0.348	0.294	P	
169	S	room 120	8/28/2008	0.199	0.307	P								8/9/2011	0.288	0.327	P	
170	S	Gym first floor, training room 131					9/9/2008	0.314	0.047	P				8/9/2011	0.097	0.04	P	
171	B	Gym first floor,, men's locker room					9/9/2008	0.313	0.055	P				8/9/2011	0.145	0.077	P	
172	B	Gym first floor, women's locker room												8/9/2011	0.152	0.072	P	
173	B	Gym first floor, weight room 125					9/9/2008	0.364	0.792	P				8/9/2011	0.082	0.095	P	
174	B	Gym first floor, hallway, left					9/9/2008	0.166	0.072	P				8/9/2011	0.1	0.061	P	
175	B	Gym first floor, hallway, right					9/9/2008	0.105	0.08	P				8/9/2011	0.084	0.062	P	
176	S	concession 112																
177	S	counselor center, work room, 104					9/9/2008	0.184	0.123	P				8/9/2011	0.366	0.37	P	
178	B	outside auditorium, left																
179	B	outside auditorium, right																
180	S	Gym, second floor, concessions									9/19/2008	0.131	0.146	P	8/9/2011	0.133	0.078	P
181	B	Gym, second floor, hallway, left					9/9/2008	0.231	0.213	P				8/9/2011	0.079	0.076	P	
182	B	Gym, second floor, hallway, middle					9/9/2008	0.217	0.194	P				8/9/2011	0.08	0.077	P	
183	B	Gym, second floor, hallway, right					9/9/2008	0.214	0.174	P				8/9/2011	0.084	0.078	P	
186	B	3rd floor, hallway, outside 317, left									9/19/2008	0.227	0.199	P	8/9/2011	0.452	0.261	P
187	B	3rd floor, hallway, outside 317, right									9/19/2008	0.186	0.213	P	8/9/2011	0.341	0.222	P
188	S	room 106, middle sink																

Table 4. Copper Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
101	B	first floor, hallway by 103,	7/11/2014	0.233	0.223	P									4/11/2018	0.091	0.133	P	P	None
102	B	first floor, hallway by 103, bottle filler	7/11/2014	0.229	0.223	P									4/11/2018	0.155	0.204	P	P	None
103	S	room 105													4/11/2018	0.558	0.333	P	P	None
104	S	room 106, west wall, right	7/11/2014	0.307	0.245	P									4/11/2018	0.356	0.077	P	P	None
105	S	room 106, west wall, middle	7/11/2014	0.318	0.237	P									4/11/2018	0.386	0.068	P	P	None
106	S	room 106, west wall, left	7/11/2014	0.291	0.195	P									4/11/2018	0.342	0.067	P	P	None
107	S	room 106, south wall	7/11/2014	0.273	0.237	P									4/11/2018	0.203	0.346	P	P	None
108	S	room 106, east wall, south end, right	7/11/2014	0.267	0.227	P									4/11/2018	0.353	0.081	P	P	None
109	S	room 106, east wall, south end, middle	7/11/2014	0.286	0.251	P									4/11/2018	0.42	0.269	P	P	None
110	S	room 106, east wall, south end, left	7/11/2014	0.291	0.298	P									4/11/2018	0.306	0.154	P	P	None
111	Sp	room 106, east wall, north, right	7/11/2014	0.475	0.406	P													P	None
112	S	room 106, east wall, north, left													4/11/2018	0.46	0.351	P	P	None
113	B	commons, 100,	7/11/2014	0.297	0.294	P									4/11/2018	0.118	0.163	P	P	None
114	B	commons, 100, bottle filler					1/15/2016	0.069	0.067	P	2/8/2016	0.284	0.282	P	4/11/2018	0.234	0.16	P	P	None
115	S	Kitchen, east-north	7/11/2014	0.276	0.314	P									4/11/2018	0.307	0.213	P	P	None
116	S	Kitchen, East, left	7/11/2014	0.35	0.286	P									4/11/2018	0.365	0.268	P	P	None
117	Sp	Kitchen, East, right	7/11/2014	0.353	0.24	P									4/11/2018	0.339	0.199	P	P	None
118	K	Kitchen, Kettle	7/11/2014	0.387	0.336	P									4/11/2018	0.382	0.199	P	P	None
119	S	kitchen, middle	7/11/2014	0.332	0.379	P									4/11/2018	0.381	0.396	P	P	None
120	S	workroom 108	7/11/2014	0.243	0.349	P									4/11/2018	0.359	0.357	P	P	None
121	S	Kitchen, West wall, right	7/11/2014	0.288	0.366	P									4/11/2018	0.325	0.417	P	P	None
122	S	first floor, staff lounge, 109	7/11/2014	0.162	0.201	P									4/11/2018	0.331	0.138	P	P	None
123	S	custodian break room	7/11/2014	0.154	0.156	P									4/11/2018	0.185	0.195	P	P	None
124	S	room 119, student store																	P	None
125	S	room 200C, library office	7/11/2014	0.284	0.305	P									4/11/2018	0.33	0.199	P	P	None
126	S	room 237	7/11/2014	0.242	0.254	P									4/11/2018	0.301	0.256	P	P	None
127	S	room 239	7/11/2014	0.309	0.413	P									4/11/2018	0.054	0.052	P	P	None
128	S	room 244	7/11/2014	0.282	0.306	P									4/11/2018	0.415	0.394	P	P	None
129	B	2nd floor, hallway by staff women restroom, left	7/11/2014	0.218	0.19	P									4/11/2018	0.148	0.176	P	P	None
130	B	2nd floor, hallway by staff women restroom, right	7/11/2014	0.231	0.21	P									4/11/2018	0.268	0.191	P	P	None
131	S	room 211	7/11/2014	0.252	0.174	P									4/11/2018	0.15	0.176	P	P	None
132	S	room 213													4/11/2018	0.385	0.307	P	P	None
133	S	staff conference room	7/11/2014	0.248	0.232	P									4/11/2018	0.312	0.2	P	P	None
134	S	room 215	7/11/2014	0.374	0.257	P									4/11/2018	0.084	0.078	P	P	None
135	S	room 216	7/11/2014	0.233	0.277	P									4/11/2018	0.256	0.127	P	P	None
136	B	2nd floor, hallway, cross from room 218, left	7/11/2014	0.378	0.339	P									4/11/2018	0.336	0.155	P	P	None
137	B	2nd floor, hallway, cross from room 217, right	7/11/2014	0.335	0.285	P									4/11/2018	0.329	0.32	P	P	None
138	B/S	room 217, Jazz, choir room	7/11/2014	0.356	0.345	P									4/11/2018	0.313	0.266	P	P	None
139	S	room 219, band room	7/11/2014	1.56	3.07										4/11/2018	1.46	1.28		F	PS
140	S	room 228	7/11/2014	0.219	0.336	P									4/11/2018	0.289	0.328	P	P	None
141	S	room 230	7/11/2014	0.263	0.281	P									4/11/2018	0.25	0.215	P	P	None
143	S	room 236	7/11/2014	0.344	0.193	P									4/11/2018	0.304	0.155	P	P	None
144	B	3rd floor, by staff women restroom, left	7/11/2014	0.278	0.158	P									4/11/2018	0.265	0.207	P	P	None
145	B	3rd floor, by staff women restroom, right	7/11/2014	0.37	0.182	P									4/11/2018	0.292	0.254	P	P	None
152	S	staff conference	7/11/2014	0.267	0.233	P									4/11/2018	0.294	0.246	P	P	None
153	S	room 326, east	7/11/2014	0.256	0.249	P									4/11/2018	0.278	0.201	P	P	None

154	S	room 326, south, left	7/11/2014	0.272	0.251	P								4/11/2018	0.336	0.179	P	P	None
155	S	room 326, south, right	7/11/2014	0.266	0.304	P								4/11/2018	0.309	0.206	P	P	None
156	S	room 331 staff conference	7/11/2014	0.252	0.266	P								4/11/2018	0.248		P	P	None
157	S	first floor, conference room	7/11/2014	0.353	0.328	P								4/11/2018	0.307	0.415	P	P	None
158	S	nurse office, 102A	7/11/2014	0.374	0.315	P								4/11/2018	0.324	0.355	P	P	None
159	S	nurse office, 102E	7/11/2014	0.274	0.2	P								4/11/2018	0.259	0.341	P	P	None
160	S	nurse office, 102F	7/11/2014	0.233	0.201	P								4/11/2018	0.244	0.345	P	P	None
161	S	nurse office, 102H	7/11/2014	0.199	0.205	P								4/11/2018	0.188	0.294	P	P	None
162	S	main office, work room, room 101E	7/11/2014	0.309	0.333	P								4/11/2018	0.325	0.337	P	P	None
163	Sp	Kitchen, west wall, north sink -- dishwashing sink	7/11/2014	0.425	0.373	P								4/11/2018	0.344	0.366	P	P	None
169	S	room 120	7/11/2014	0.316	0.425	P								4/11/2018	0.344	0.343	P	P	None
170	S	Gym first floor, training room 131	7/11/2014	0.051	0.049	P								4/11/2018	0.113	0.056	P	P	None
171	B	Gym first floor,, men's locker room	7/11/2014	0.094	0.04	P								4/11/2018	0.137	0.106	P	P	None
172	B	Gym first floor, women's locker room	7/11/2014	0.104	0.052	P								4/11/2018	0.186	0.094	P	P	None
173	B	Gym first floor, weight room 125	7/11/2014	0.097	0.092	P								4/11/2018	0.137	0.141	P	P	None
174	B	Gym first floor, hallway, left	7/11/2014	0.046	0.037	P								4/11/2018	0.125	0.11	P	P	None
175	B	Gym first floor, hallway, right	7/11/2014	0.058	0.044	P								4/11/2018	0.075	0.064	P	P	None
176	S	concession 112	7/11/2014	0.267	0.308	P												P	None
177	S	counselor center, work room, 104	7/11/2014	0.303	0.352	P								4/11/2018	0.504	0.398	P	P	None
178	B	outside auditorium, left												4/11/2018	0.267	0.285	P	P	None
179	B	outside auditorium, right	7/11/2014	0.313	0.313	P								4/11/2018	0.326	0.295	P	P	None
180	S	Gym, second floor, concessions	7/11/2014	0.107	0.132	P												P	None
181	B	Gym, second floor, hallway, left	7/11/2014	0.07	0.07	P								4/11/2018	0.121	0.108	P	P	None
182	B	Gym, second floor, hallway, middle	7/11/2014	0.067	0.056	P								4/11/2018	0.101	0.095	P	P	None
183	B	Gym, second floor, hallway, right	7/11/2014	0.09	0.075	P								4/11/2018	0.115	0.092	P	P	None
186	B	3rd floor, hallway, outside 317, left	7/11/2014	0.386	0.351	P								4/11/2018	0.305	0.298	P	P	None
187	B	3rd floor, hallway, outside 317, right	7/11/2014	0.423	0.309	P								4/11/2018	0.32	0.227	P	P	None
188	S	room 106, middle sink	7/11/2014	0.273	0.34	P								4/11/2018	0.465	0.095	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling			Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				Follow-up Sampling 5				Summary Status			
Fixture ID	Type	Location	Date	1st Draw	Flush 2m	Pass /Fail	Date	1st Draw	Flush 2m	Pass /Fail	Date	1st Draw	Flush 2m	Pass /Fail	Date	1st Draw	Flush 2m	Pass /Fail	Date	1st Draw	Flush 30s	Pass /Fail	Date	1st Draw	Flush 2m	Pass /Fail	Pass /Fail	Status	
101	B	first floor, hallway by 103, room 106, east wall, south end, middle	8/28/08		0.099	P									7/11/14		0.05	P									P	None	
109	S	commons, 100, bottle filler																	1/15/16	0.053	0.052	P	4/11/18		<0.05	P	P	None	
114	B	Kitchen, East, left																					4/11/18		<0.05	P	P	None	
116	S	first floor, staff lounge, 109									8/9/11		<0.05	P													P	None	
122	S	custodian break room	8/28/08		0.144	P									7/11/14		0.062	P									P	None	
123	S	room 237	8/28/08		0.167	P																					P	None	
126	S	2nd floor, hallway by staff women restroom, right	8/28/08		0.078	P					8/9/11		<0.05	P													P	None	
130	B	room 211	8/28/08		0.08	P									7/11/14		<0.05	P									P	None	
131	S	room 213																					4/11/18		<0.05	P	P	None	
132	S	room 219, band room	8/28/08		0.178	P																					P	None	
139	S	room 228	8/28/08		0.055	P					8/9/11		0.06	P													P	None	
140	S	room 230													7/11/14		<0.05	P									P	None	
141	S	room 236																					4/11/18		<0.05	P	P	None	
143	S	3rd floor, by staff women restroom, right									8/9/11		0.051	P													P	None	
145	B	starff conference	8/28/08		0.065	P									7/11/14		<0.05	P									P	None	
152	S	room 326, south, right	8/28/08		0.05	P																					P	None	
155	S	room 331 staff conference																					4/11/18		<0.05	P	P	None	
156	S	nurse office, 102H									8/9/11		<0.05	P													P	None	
161	S	main office, work room, room 101E	8/28/08		0.111	P									7/11/14		<0.05	P									P	None	
162	S	Gym first floor, training room 131																					4/11/18		<0.05	P	P	None	
170	S	Gym first floor,, men's locker room					9/9/08		0.246	P																	P	None	
171	B	Gym first floor, weight room 125					9/9/08		0.403	P																	P	None	
173	B	Gym first floor, hallway, right									8/9/11		0.087	P													P	None	
175	B	counselor center, work room, 104													7/11/14		<0.05	P					4/11/18		<0.05	P	P	None	
177	S	Gym, second floor, concessions									8/9/11		0.098	P													P	None	
180	S	Gym, second floor, hallway, left					9/9/08		0.146	P					7/11/14		0.056	P									P	None	
181	B	room 106, middle sink																					4/11/18		<0.05	P	P	None	
188	S																												None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room, main building basement	Arsenic	11-Apr-18	2 ppb	P
00	SE	boiler room, main building basement	Cadmium	11-Apr-18	1 ppb	P
00	SE	boiler room, main building basement	Chlorine	09-Sep-04	0.5 ppm	P
00	SE	boiler room, main building basement	Copper	11-Apr-18	0.197 ppm	P
00	SE	boiler room, main building basement	E coli	09-Sep-04	<1 Colonies	P
00	SE	boiler room, main building basement	Iron	11-Apr-18	<0.05 ppm	P
00	SE	boiler room, main building basement	Lead	11-Apr-18	1 ppb	P
00	SE	boiler room, main building basement	Total Coliforms	05-Oct-09	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.